



PHOTOGRAPHIC LOG

STATE OF CALIFORNIA
 DEPARTMENT OF FORESTRY AND FIRE PROTECTION
 LE 75p (REV. 7/2011)

INCIDENT NUMBER
15CALNU008670
CASE NAME
VALLEY

DAY	MONTH	DATE	YEAR	COUNTY	REGION	UNIT	CASE NUMBER
Thrs.	Sept.	17	2015	Lake	CNR	LNU	

PHOTO ID	DATE TAKEN	TIME TAKEN	TAKEN BY	PHOTO DESCRIPTION
IMG_0001	9/17/15	11:04 a.m.	J. Engel	Heel of fire, looking westerly.
IMG_0002	9/17/15	11:04 a.m.	J. Engel	Heel of fire, looking southwesterly.
IMG_0003	9/17/15	11:04 a.m.	J. Engel	Heel of fire, looking southerly.
IMG_0004	9/17/15	11:04 a.m.	J. Engel	Heel of fire, looking southeasterly.
IMG_0005	9/17/15	11:04 a.m.	J. Engel	Heel of fire, looking easterly.
IMG_0006	9/17/15	11:05 a.m.	J. Engel	Taken from creek, near heel of fire, looking southwesterly.
IMG_0007	9/17/15	11:10 a.m.	J. Engel	Taken from creek/hose line, looking southwesterly at burnt power pole in center of picture and blue water tank on left side.
IMG_0008	9/17/15	11:10 a.m.	J. Engel	Taken from creek/hose line, looking northwesterly toward heel of the fire.
IMG_0009	9/17/15	11:10 a.m.	J. Engel	Taken from hose line, which would have been the east flank of the fire at the time of the suppression action, looking northwesterly toward heel of the fire.
IMG_0010	9/17/15	11:11 a.m.	J. Engel	Taken from hose line, which would have been the east flank of the fire at the time of the suppression action, looking southeasterly.
IMG_0011	9/17/15	11:11 a.m.	J. Engel	Angle of char indicator showing advancing fire from right to left.
IMG_0012	9/17/15	11:19 a.m.	J. Engel	Taken from near creek/hose line, toward destroyed residence, looking southwesterly. Shows what was likely the heel of the fire when suppression action taken.
IMG_0013	9/17/15	11:19 a.m.	J. Engel	Taken from near creek/hose line, looking easterly. Shows what was likely the heel and east flank of the fire when suppression action taken.
IMG_0014	9/17/15	11:19 a.m.	J. Engel	Taken from near creek/hose line, looking southwesterly at water tank and burnt through, 3 crossarm, corner, power pole.

IMG_0015	9/17/15	11:19 a.m.	J. Engel	Close-up of corssarms on burnt through corner power pole.
IMG_0016	9/17/15	11:20 a.m.	J. Engel	Looking westerly toward the destroyed residence.
IMG_0017	9/17/15	11:24 a.m.	J. Engel	Close-up of corssarms on burnt through corner power pole.
IMG_0018	9/17/15	11:24 a.m.	J. Engel	Burnt through corner power pole.
IMG_0019	9/17/15	11:25 a.m.	J. Engel	Close-up of crossarms on burnt through corner power pole.
IMG_0020	9/17/15	11:25 a.m.	J. Engel	Close-up of conductors, deadends, jumpers, connectors, and insulators, on crossarms of the burnt through corner power pole.
IMG_0021	9/17/15	11:25 a.m.	J. Engel	Close-up of conductor, deadend, jumpers, and connectors on crossarm of the burnt through corner power pole.
IMG_0022	9/17/15	11:25 a.m.	J. Engel	Close-up of conductor, deadend, jumper, connector and insulator on crossarm of the burnt through corner power pole.
IMG_0023	9/17/15	11:25 a.m.	J. Engel	Close-up of conductor, deadend, jumper, connector and insulator on crossarm of the burnt through corner power pole.
IMG_0024	9/17/15	11:25 a.m.	J. Engel	Close-up of conductor, deadend, jumper, connector and insulator on crossarm of the burnt through corner power pole.
IMG_0025	9/17/15	11:25 a.m.	J. Engel	Close-up of deadend, jumper, connector and insulator on crossarm of the burnt through corner power pole.
IMG_0026	9/17/15	11:25 a.m.	J. Engel	Close-up of conductors, deadends, jumpers, connectors, and insulators, on crossarms of the burnt through corner power pole.
IMG_0027	9/17/15	11:33 a.m.	J. Engel	Taken from southwest of destroyed residence, looking southeasterly at burnt power pole in center of picture and blue water tank on right side.
IMG_0028	9/17/15	11:33 a.m.	J. Engel	Power pole with transformer locate near southwest corner of the destroyed residence.
IMG_0029	9/17/15	11:33 a.m.	J. Engel	Transformer on power pole located near southwest corner of the destroyed residence.
IMG_0030	9/17/15	11:33 a.m.	J. Engel	Power pole identification number on pole with transformer, located near southwest corner of the destroyed residence.
IMG_0031	9/17/15	12:04 p.m.	J. Engel	Taken near fence/rock wall, south of SOA, looking northerly at indicator flagging.
IMG_0032	9/17/15	12:04 p.m.	J. Engel	Taken south of SOA, looking northerly at indicator flagging.
IMG_0033	9/17/15	12:05 p.m.	J. Engel	Taken near fence/rock wall, south of SOA, looking northerly at indicator flagging.

IMG_0034	9/17/15	12:05 p.m.	J. Engel	Taken near fence/rock wall, south of SOA, looking northerly at angle of char indicator on pine trees.
IMG_0035	9/17/15	12:05 p.m.	J. Engel	Close-up of angle of char indicator on pine tree.
IMG_0036	9/17/15	12:05 p.m.	J. Engel	Taken south of SOA, looking westerly at angle of char indicator on pine tree and sooting on water tank.
IMG_0037	9/17/15	12:05 p.m.	J. Engel	Taken south of SOA, looking westerly at angle of char indicators.
IMG_0038	9/17/15	12:12 p.m.	J. Engel	Taken southwest of SOA, looking northwesterly at base of corner power pole and burn indicator flagging. SOA in lower right of photograph.
IMG_0039	9/17/15	12:12 p.m.	J. Engel	Taken south of SOA, looking northerly toward heal of the fire.
IMG_0040	9/17/15	12:12 p.m.	J. Engel	Taken south of SOA, looking northeasterly toward heal and left flank of the fire.
IMG_0041	9/17/15	12:12 p.m.	J. Engel	Taken southeast of SOA, looking northwesterly toward base of the power pole, at burn indicator flagging.
IMG_0042	9/17/15	12:12 p.m.	J. Engel	Advancing fire spread indicator consisting of protection and degree of damage.
IMG_0043	9/17/15	12:12 p.m.	J. Engel	Close-up of advancing fire spread indicator consisting of protection and degree of damage.
IMG_0044	9/17/15	12:13 p.m.	J. Engel	Close-up of advancing fire spread indicator consisting of protection and degree of damage.
IMG_0045	9/17/15	12:14 p.m.	J. Engel	Taken east of SOA, looking westerly, toward water tank, at burn indicator flagging.
IMG_0046	9/17/15	12:14 p.m.	J. Engel	Close-up of backing fire spread indicator consisting of even sooting and staining around jar.
IMG_0047	9/17/15	12:15 p.m.	J. Engel	Close-up of backing fire spread indicator consisting of even protection around the jar.
IMG_0048	9/17/15	12:15 p.m.	J. Engel	Backing fire spread indicator consisting of even, low intensity burning around a stick.
IMG_0049	9/17/15	12:15 p.m.	J. Engel	Backing fire spread indicator consisting of even, low intensity burning around a stick.
IMG_0050	9/17/15	12:15 p.m.	J. Engel	Lateral fire spread indicator consisting of degree of damage/protection.
IMG_0051	9/17/15	12:15 p.m.	J. Engel	Lateral fire spread indicator consisting of degree of damage/protection.
IMG_0052	9/17/15	12:15 p.m.	J. Engel	Lateral fire spread indicator consisting of sooting/staining shown on rock.
IMG_0053	9/17/15	12:16 p.m.	J. Engel	Lateral fire spread indicator consisting of protection shown beneath rock having sooting/staining.

IMG_0054	9/17/15	12:16 p.m.	J. Engel	Lateral, backing and advancing fire spread indicators north of SOA, looking easterly. Also includes picture of guide wire from burnt through power pole.
IMG_0055	9/17/15	12:16 p.m.	J. Engel	Backing fire spread indicator consisting of sooting and even, low intensity burning around a rock.
IMG_0056	9/17/15	12:16 p.m.	J. Engel	Backing fire spread indicator consisting of sooting and even, low intensity burning around a rock.
IMG_0057	9/17/15	12:16 p.m.	J. Engel	Backing fire spread indicator consisting of sooting and even, low intensity burning around a rock.
IMG_0058	9/17/15	12:30 p.m.	J. Engel	Taken north of the SOA, looking southwesterly toward burnt through power pole and water tank.
IMG_0059	9/17/15	12:31 p.m.	J. Engel	Taken from along fence line, north of the SOA, looking southwesterly. Destroyed residence on right of photo.
IMG_0060	9/17/15	12:31 p.m.	J. Engel	Taken from along fence line, north of the SOA, looking westerly. Destroyed residence on left of photo.
IMG_0061	9/17/15	12:31 p.m.	J. Engel	Taken from along fence line, north of the SOA, looking northwesterly.
IMG_0062	9/17/15	12:31 p.m.	J. Engel	Close-up of corssarms on burnt through corner power pole.
IMG_0063	9/17/15	12:31 p.m.	J. Engel	Close-up of corssarms on burnt through corner power pole.
IMG_0064	9/17/15	12:32 p.m.	J. Engel	Close-up of conductor, deadend, jumper, and connector on crossarms of the burnt through corner power pole.
IMG_0065	9/17/15	12:32 p.m.	J. Engel	Close-up of conductor, deadend, jumper, insulator and connector on crossarms of the burnt through corner power pole.
IMG_0066	9/17/15	12:32 p.m.	J. Engel	Close-up of conductor, deadend, jumper, insulator and connector on crossarms of the burnt through corner power pole.
IMG_0067	9/17/15	12:32 p.m.	J. Engel	Close-up of conductor, deadend, jumper, insulator and connector on crossarms of the burnt through corner power pole.
IMG_0068	9/17/15	12:32 p.m.	J. Engel	Close-up of broken conductor end found on ground north of burn through power pole.
IMG_0069	9/17/15	12:45 p.m.	J. Engel	First search grid of SOA.
IMG_0070	9/17/15	12:45 p.m.	J. Engel	First search grid of SOA.
IMG_0071	9/17/15	12:45 p.m.	J. Engel	First search grid of SOA.
IMG_0072	9/17/15	12:57 p.m.	J. Engel	Second search grid of SOA.

