



California Department of Forestry and Fire Protection

INVESTIGATION REPORT

NAME: Rice Fire

CASE NO. 07-CDF-572

DATE: October 23, 2007

INCIDENT NO. 07-CA-MVU-010502

LOCATION: Rice Canyon Road, San Diego County, CA

1 - VIOLATION:

Public Resources Code Section 4293 - Except as otherwise provided in Sections 4294 to 4296, inclusive, any person that owns, controls, operates, or maintains any electrical transmission or distribution line upon any mountainous land, or in forest-covered land, brush-covered land, or grass-covered land shall, during such times and in such areas as are determined to be necessary by the director or the agency which has primary responsibility for the fire protection of such areas, maintain a clearance of the respective distances which are specified in this section in all directions between all vegetation and all conductors which are carrying electric current:

(a) For any line which is operating at 2,400 or more volts, but less than 72,000 volts, four feet.

(b) For any line which is operating at 72,000 or more volts, but less than 110,000 volts, six feet.

(c) For any line which is operating at 110,000 or more volts, 10 feet.

In every case, such distance shall be sufficiently great to furnish the required clearance at any position of the wire, or conductor when the adjacent air temperature is 120 degrees Fahrenheit, or less. Dead trees, old decadent or rotten trees, trees weakened by decay or disease and trees or portions thereof

1 that are leaning toward the line which may contact the line from the side or may
2 fall on the line shall be felled, cut, or trimmed so as to remove such hazard. The
3 director or the agency which has primary responsibility for the fire protection of
4 such areas may permit exceptions from the requirements of this section which
5 are based upon the specific circumstances involved.
6